Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	tor(s): Perkins			12-Aug-20
Company/Owner: Intermou		untain Gas Company	Unit/OPID:	8160
Company/Owner.	Intermo	antain das Company	Office of its.	0100
Inspection Type & Time (1	day)	Total	Inspection Days:	1
Standard: Construction: 1 Training: (T)(D) Integrity Management: Incident:				
M/M: Follow-up: OQ: Damage Prevention: D&A:				
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
12 Aug 2020: (1.0 Construction) Observed a Das-co crew installing a new ¾" service lines and stubs at 561 Heliopolis Way, Star Idaho and 8362 Fountain Spring Ct, Middleton Idaho. All procedures were followed. Typed up report Areas observed during this project were: Excavating, line locating, plastic joining, backfilling/bedding, pressure testing and EFV test. Attachments: IPUC Form 4 Construction Inspections				
Das-co daily Itineraries locate OQ's for all observed employ	ed in file for the proj			
Corrective Action Required: Yes No		ow-up Required:	by (date):	Х
Inspector (Lead):	100	11/1	Date:	
Bruce Perkins		DISA-	8/12/2020	
Reviewer: Date:				
Darrin Ulmer	Water	MIV	24 Ruh 2	20